

## OAP900 Firmware version 1.6.0 Release Note

### Fixed

- Fixed LAN2 ping fail issue
- Fixed Guest Network Traffic shaping doesn't work issue
- Fixed Guest Portal function don't work issue
- Fixed Client Bridge Mode when PC connect with DUT LAN2 that it will not get connection.
- Fixed Client Bridge Mode connection issue when using "WPA/WPA2 Mixed" and "TKIP/AES Mixed" encryption type
- Fixed LED and Buzzer icon cannot effect issue
- Fixed NMS mode display issues that the Managed AP still show AP mode.
- Fixed NMS mode data sync issue that controller cannot change AP Group for OAP900
- Fixed NMS mode data sync issue that controller cannot configure "Auto Pilot Sensitivity" for OAP900.
- Fixed NMS mode data sync issue that controller cannot configure "Auto Pilot Interval" for OAP900.
- Fixed NMS mode data sync issue that controller cannot configure RADIUS group for OAP900.

### New Features

-

### Modification

-